
REPORTING 6.1.5

Report temperature measurements in the data base to the nearest 0.5°C.

- ▶ For studies for which greater accuracy is desired, temperatures can be reported to the accuracy requested, provided the thermometer has been calibrated to that accuracy.
- ▶ Enter field measurements of air and water temperature on NWQL Analytical Services Request forms, and in the data base under the correct parameter code.
- ▶ Record the accuracy range of the instrument in the data base, if possible. Report accuracy range with the published values.

Report only those water temperature values that were measured in situ.